



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program

Reviewed: CH

August 19, 2009

Mine Name: Lime Ridge	Permit Number: M/037/0081
Operator Name: Holliday Construction	Inspection Date: June 2, 2009
Inspector(s): Wayne Western	Time: 5:30 PM 6:15 PM
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$57,788, renewal date August 1, 2011

Permit fee: Paid July 2, 2009

Purpose of Inspection:

This was a routine inspection.

Directions:

Access to the site is on County Road 2351. Approximately 15 miles west of Bluff Utah on Highway 163.

Inspection Summary:

The site was clean and there were no signs of erosion. There are some small pits with vegetation in the bottom. The present of vegetation suggests that activities in those areas have not occurred for a few years. The Permittee stated in the annual report that 3,545 tons of ore were produced. The Permittee stated in the annual report that no reclamation had occurred

Conclusions and Recommendations:

The site is stable and no further action is needed.

Inspector's Signature

A handwritten signature in blue ink, appearing to read "Arden M. [unclear]", is written over a horizontal line.

whw

cc: Holliday Construction
John Blake, SITLA

O:\M037-SanJuan\M0370081-LimeRidge\Inspections\ins-06032009.doc



